

PAX RIVER HCAT ROD TESTING

Jeff Gribble / James Magno

July 2004 HCAT

maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to ompleting and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding ar DMB control number.	ion of information. Send comments is arters Services, Directorate for Infor	regarding this burden estimate of mation Operations and Reports	or any other aspect of the 1215 Jefferson Davis	is collection of information, Highway, Suite 1204, Arlington		
1. REPORT DATE JUL 2004		2. REPORT TYPE		3. DATES COVE 00-00-2004	red I to 00-00-2004		
4. TITLE AND SUBTITLE		5a. CONTRACT	NUMBER				
Pax River HCAT I		5b. GRANT NUMBER					
			5c. PROGRAM ELEMENT NUMBER				
6. AUTHOR(S)			5d. PROJECT NUMBER				
					5e. TASK NUMBER		
					5f. WORK UNIT NUMBER		
	ZATION NAME(S) AND AE Center,22347 Ceda	ent	8. PERFORMING ORGANIZATION REPORT NUMBER				
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)			
				11. SPONSOR/M NUMBER(S)	ONITOR'S REPORT		
12. DISTRIBUTION/AVAIL Approved for publ	LABILITY STATEMENT ic release; distributi	on unlimited					
13. SUPPLEMENTARY NO 24th Replacement Sponsored by SER	of Hard Chrome Pla	ating Program Revi	ew Meeting, July	20-21, 2004,	Park City, UT.		
14. ABSTRACT							
15. SUBJECT TERMS							
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF		
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	10	RESPONSIBLE PERSON		

Report Documentation Page

Form Approved OMB No. 0704-0188



NAVAIR PAX Work Status:

- Currently Planning the Functional Rod/Seal Testing at PAX Hydraulic Lab.
 - Rods have been Received at PAX
 - Evaluated Past Testing Seal Types.
- Test Primarily Based on HCAT Joint Test Protocol Dated 30 September 2003. JTP has been Modified to Include:
 - High Temp at 275 F (not 300 F)
 - •MIL-PRF-83282 Fluid Used (not MIL-PRF-87257)
- JTP Will Validate HVOF Thermal Spray Coatings as Replacements for Hard Chrome Plating on Hydraulic/Pneumatic Actuators.





Test Apparatus:

- Located at NAVAIR Patuxent River Hydraulic Lab.
- Master hydraulic piston drives four test rods. Each rod passes through two blocks ("Near End Block" and "Far End Block").
- Apparatus is mounted inside an environmental chamber capable of maintaining a temperature between -65° and +300° F.
- The master piston passes through a sealed port on the environmental chamber.
- The hydraulic power supply is located outside the chamber for increased reliability of the test hardware.
- Hydraulic lines to the fixture are single-ended and thus should not heat or cool the test hardware.






Test Rod and Block/Seal Configuration:

• There are two seal configurations per block and two blocks per rod so that 16 rod/seal configurations are being evaluated per test.

• Primary seals are indicated in blue and the secondary seals in

magenta.










Stroke Profile:


• Full Stroke (3.5" Stroke, 1.5 second Period, 20 Minute Duration per Hour)

• Superimposed Dither (2" Main Stroke, 0.25" Dither stroke, 4 second Period, 4 Hz Frequency, 20 Minute Duration per Hour)

• Dither (0.25" Dither stroke, 4 Hz Frequency, 20 Minute Duration per Hour)







Jeff Gribble / James Magno NAVAIR-PAX Hydraulic Systems

HCAT July 2004 Park City, Utah





Temperature Profile:

Day No.	Hours	Temp (F)	
1	8	160	
2	8	200	
3	8	160	
4	8	225	
5	8	160	
6	8	250	
7	8	160	
8	8	250	
9	8	160	
10	8	275	
11	8	160	
12	8	275	
13	4	-40	

Notes:

- 1. Between Test Days the Temperature Shall be 0°F to Evaluate Static Leakage at Startup.
- 2. Total Cycles will Total 1,040,000 and Travel 13.6 miles. Total run time will be 100 hours.





Test Configuration (Phase 1):

Rod No.	Rod Description	Block Location	Gland Location	Seal Description	Vendor
HVOF applie Ra of 4 or be	HVOF applied WC/CoCr, ground with progressively finer wheels to	Near End	Inboard	MIL-P-83461 O-ring with PTFE Capstrip	TBD
	Ra of 4 or better		Outboard	MIL-P-83461 O-ring with 2 Backup Rings	TBD
		Far End	Inboard	Fluorosilicon O-ring with PTFE Capstrip	TBD
			Outboard	Spring energized PTFE seal	TBD
or so wheel, leavi with a D-17 stone produce Green To	HVOF applied WC/CoCr, ground to dimension with a 180 or 220	Near End	Inboard	MIL-P-83461 O-ring with PTFE Capstrip	TBD
	or so wheel, leaving an Ra of 16-24, followed with superfinishing with a D-17 stone, followed by a felt pad and diamond paste, to		Outboard	MIL-P-83461 O-ring with 2 Backup Rings	TBD
	produce Green Tweed recommended roughness parameters,	Far End	Inboard	Fluorosilicon O-ring with PTFE Capstrip	TBD
	Ra<= 4 micron, Tp = 60-90% @ 0.25 Rz.		Outboard	Spring energized PTFE seal	TBD
wheel, lea with progr	IVOF applied WC/CoCr, ground to dimension with a 320 or so	Near End	Inboard	MIL-P-83461 O-ring with PTFE Capstrip	TBD
	wheel, leaving an Ra of 4-8 micron, followed with superfinishing with progressively finer stones, to produce an Ra of 1 micron or		Outboard	MIL-P-83461 O-ring with 2 Backup Rings	TBD
	etter, with essentially no peaks and valleys.	Far End	Inboard	Fluorosilicon O-ring with PTFE Capstrip	TBD
			Outboard	Spring energized PTFE seal	TBD
4 Ba	Baseline chrome plated rod, ground to an Ra of 12-16 micron.	Near End	Inboard	MIL-P-83461 O-ring with PTFE Capstrip	TBD
			Outboard	MIL-P-83461 O-ring with 2 Backup Rings	TBD
		Far End	Inboard	Fluorosilicon O-ring with PTFE Capstrip	TBD
			Outboard	Spring energized PTFE seal	TBD

Primary and Secondary Seals are identical for each different seal type.





Test Evaluation and Reporting:

- Each rod will be inspected and characterized before testing (optical microscopy and surface profilometry).
- •Hydraulic fluid leakage from each block will be measured and recorded.
- Fluid that is collected will be retained for possible analysis for seal and coating constituents.
- Seals will be weighed and measured, with the results recorded.
- A report will document the testing conducted, the results of the characterization of the rods and seals, and the results of the measurements of fluid leakage and analysis.





F/A-18 C/D Stabilator Testing:

- Based on laboratory results, fluorocarbon static seals and PTFE spring energized dynamic seals were selected.
- Rebuild kits for F/A-18 C/D stabilator actuator were developed by seal vendors using hardware dimensions.
- Endurance testing of seal kits from three vendors had no external leakage and acceptable internal leakage after endurance testing. Posttest leakage was within ATP limits.
- •Follow-on testing evaluated HVOF coated rod against these seals.
- Leakage performance was equivalent to chrome plated rod.
- STAB Actuator Testing is Complete. Finalizing Test Report for ECP.

HCAT July 2004 Park City, Utah





F/A-18 C/D Trailing Edge Flap:

- Same dynamic and static seal materials used for TEF as proven on STAB.
- Side by side design allows one chrome rod and one HVOF rod to evaluate seals against both rod surfaces.
- Endurance testing of TEF has begun and is 2/3 complete. Currently awaiting a different seal configuration to resume the evaluation.

